# RI Department of Environmental Management Environmental Land Usage Restriction (ELUR) Annual Compliance Evaluation Form (Please

type or print)

Site N	fame: Gorham – P	arcel A	Property Owner: Providence Redevelopment Agency		
RIDEM File No.: Case No. 97-030			Owner Mailing Address:		
RIDEM Project Manager: Joe Martella			444 Westminster Street, Providence, RI 02903		
	Recording Date		Inspection Date: December 10, 2019		
	~	mber: (401) 680-8418	E-Mail: cdupre@providenceri.com		
of any	y active remedia		appropriate for use on sites that require the use SDS, ongoing air or groundwater monitoring, tranted by the Department.		
1. Site	e Description				
a.	Site Address:	77 Reservoir Ave			
		Providence, RI 02907			
b.	Plat: <u>51</u>	Lot(s): <u>326</u>			
		No describe the portion of the	e property subject to the ELUR:		
d.	X Resident X Ground X Exposu X Infiltra X Subsur	re to Site Soils tion of Water face Structures Please Explain):	escribed in the SMP shall not be disturbed.		
2. Gr	oundwater				
a.	Are there any k	nown or observed groundwa	nter wells present?		
b.	Are these well(	s) used for drinking water? NoX Not	Applicable		
	If no, please st	ate what they are used for (i	.e. irrigation, cooling, etc.):		

c.	c. Are there environmental monitoring wells present? XYesNo		
3. En	gineered Controls (e.g. asphalt, concrete, building foundations, landscaped areas, etc.)		
a.	Please provide a brief description of the engineered control(s) (e.g. building foundations, one foot of clean fill over a geotextile liner, etc.):  3. Strip-mall concrete slab building foundations  4. Expansive asphalt parking surface  5. Numerous landscaped islands		
b.	Overall Condition of Engineered Control(s)  Good X Non-compliant Acceptable Not Applicable (Sites where only groundwater is restricted)		
c.	Are there any areas on the property that have broken concrete, cracked asphalt, potholes, eroded landscaping, etc.?  X Yes No  If yes:		
2.	Please provide a description of the area(s) of concern:  Substantial areas of asphalt cracking. Some areas appear to have been filled previously, but repairs needed throughout. Areas of ponding observed, one being substantial, implicating surface runoff may be slowly infiltrating into cap and ontaminated soils.  Could water infiltrate through these areas into underlying contaminated soils?  X Yes No N/A; Infiltration Not Restricted  When will the area(s) of concern be repaired? TBD		
d.	Has there been any soil disturbance or excavation into the cap (engineered control) in the last year?  Yes X No  If yes:  How large was the area of disturbance?		
	Please provide the reason or cause for disturbance or excavation:		

	Was this disturbance or excavation approved by the Department?  Yes, Date of Approval:
	No
	Was the Soil Management Plan (SMP) properly followed?  Yes No N/A
	If no, please explain:
	Was any soil taken offsite? Yes No X N/A
e.	Within the past year has there been any construction at the property unauthorized by the department?  Yes X No
	If yes:
	Please explain:
	Did this construction disturb site soils, the existing building or capped surfaces (asphalt, concrete, or landscaped areas)?  Yes No  If yes, please specify: N/A
	if yes, please specify.
f.	Have there been any subsurface structures (underground storage tanks, below grade foundations, septic systems, storm water systems, french drains, etc.) constructed or installed since the remediation was completed? YesXNo
	If yes:
	Please Explain:
	Was permission of the Department's Office of Waste Management obtained?  Yes, Date of Approval: No

g.	Condition of landscaped areas
	X Good Acceptable Non-compliant N/A
h.	Does the cap effectively limit exposure to contaminated subsurface soil?  YesX No N/A
4. Pr	operty Use
a.	Are there any residential uses on the property (i.e. houses, apartments or condominiums, etc.) except as previously agreed upon by the Department?  YesX No
	If yes, please explain:
b.	Are there any schools, daycare facilities or recreational facilities on the property except as previously agreed upon by the Department? YesXNo
	If yes, please explain:
c.	Has the property use changed in any way since the ELUR was recorded?  Yes X No  If yes, please explain:
5. Fe	ncing (if applicable)
a.	Overall Condition of the Fencing  Good Acceptable Non-compliant x No Fence Required
b.	Does the fencing effectively limit the ELUR area?  Yes No X N/A
5. Ov	verall Assessment
D	oes this site meet the standard imposed in the ELUR?  Compliant X Non-compliant

7.	<b>Observations</b>	comments.	and	areas of	concern

The cap inspection occurred within 24 hours of a rain event. The landscaped areas showed no signs of erosion and appeared to function adequately as a cap. Pavement cracking was evident throughout the site. Some cracks looked to have been previously filled, however most needed repair/refilling. See attached Photo Location Figure and photos. The photos attached do not show all areas of pavement cracking but are representative of conditions around the site. Areas of puddling were also present at different areas of the site. While most were smaller, there was a large puddling area adjacent to the previous gas station pump area. These areas of puddling require pavement removal, installation and grading of structural fill material, and repaving to correct the existing problems. See attached Photo Location Figure and photos showing the aforementioned areas of puddling.

8. Please attach photos that document compliance with the ELUR, potential areas of concern, and the current state of the engineered controls.

Certification of Property Owner				
I Bonne Nickerson certify to the Evaluation Form is a complete and an accurate facts concerning the Environmental Land Us	best of my knowledge that this Annual Compliance ate representation of the site and contains all known e Restriction imposed on the site.			
Signature	Owning Company (If applicable)			
Bonnie Nickerson	Executive Director Title			
	Title			
5/24/20				
Date				
	e best of my knowledge that this Annual Compliance representation of the site and contains all known e Restriction imposed on the site.			
Michael Welker	Wood Environment & Infrastructure Solutions, Inc.			
Signature	Environmental Company Name			
Michael Wilkinson	Project Engineer			
Printed Name	Title			
Contact Information (If Applicable)				
(401) 648-9245	michael.wilkinson@woodplc.com			
Telephone Number	E-Mail Address			



Photo 2: Puddling (see Photo Location Figure)



Photo 3: Example of cracking and previous fill efforts (see Photo Location Figure)



Photo 14: Puddling (see Photo Location Figure)



Photo 15: Puddling (see Photo Location Figure)



Photo 16: Puddling (see Photo Location Figure)



Photo 18: Example of cracking and previous fill efforts (see Photo Location Figure)



Photo 24: Puddling (see Photo Location Figure)



Photo 26: Puddling (see Photo Location Figure)



Photo 30: Pavement cracking (see Photo Location Figure)





Photo 31: Puddling (see Photo Location Figure)



Photo 36: Puddling (see Photo Location Figure)



#### RECEIVED:

Providence
Received for Record
Jun 04:2015 at 01:01
Document Num: 001186 Sense
John A Flurphy
John A Flurphy
Ader of Deed's Minimum (Inches of septial personal or concerns to Asset of the Asset of the

Building

Former Gottam Manufacturing Site 333 Adelaide Avenue Provintence, Ri



Parcel A Cap

Project 3852-13-0029

Exhibit B Figure 1