



October 3, 2006

081-12152-03

Mr. Jeffrey Crawford
Rhode Island Department of Environmental Management
Office of Waste Management
235 Promenade Street
Providence, RI 02908-5767

Subject: Springfield Street School Complex, 50 Springfield Street, Providence, RI

Dear Mr. Crawford:


We are submitting this letter and the attached photographs to document that an area of soil settling reported in the most recent quarterly monitoring report has been repaired. The small hole was observed adjacent to the concrete berm surrounding the transformer behind the middle school. The orange snow fence barrier was not observed. Repairs were made by the Providence School Department on September 21, 2006.

Sincerely,

Donna H. Pallister, P.E., L.S.P.
Senior Engineer

CC: S. Tremblay, Providence School Department

RECEIVED
D.E.M./O.W.M.
2006 OCT -5 P 12:09



1

Photograph of hole observed on September 6, 2006



2

Photograph of same area after repairs (photographed on 10/3/06)