

Sent Via Email

## **GZA GeoEnvironmental, Inc.**

530 Broadway Providence, Rhode Island 02909 Phone - (401) 421-4140 Fax - (401) 751-8613

TO:

Joseph Martella- RIDEM

James Ball, RIDEM

FROM:

Meg Kilpatrick – GZA

CC:

Michele Leone - NGRID

James Clark - GZA

DATE:

April 19, 2010

FILE NO.:

05.0043654.00

RE:

Site Response Action Status Report - March 1, 2010 through March 31, 2010

Former Tidewater Facility Pawtucket, Rhode Island RIDEM Case No. 95-022

The following summarizes response actions completed at the above-referenced site for the period March 1, 2010 through March 31, 2010. Activities associated with the *Supplemental Site Investigation Work Plan* (SSWIP) dated November 23, 2009 were on-going. Further details on these, as well as other activities performed during this period are summarized below.

## SITE ACTIVITIES PERFORMED

- Field work associated with the planned treatment and discharge of accumulated storm water within
  former Gas Holders No. 7 and 8, including mobilization and set up of treatment system components.
  This work is being performed in accordance with RIPDES Permit No. RIG85E001 issued by RIDEM
  on December 9, 2009 and CRMC Assent No. A2009-11-059 dated December 14, 2009.
- Completion of weekly Site inspections to document Site security conditions and sheen observations.

## **FUTURE RESPONSE ACTION WORK/SCHEDULE**

- Continue subsurface exploration program. Abutter notification letters were mailed out on April 16, 2010 via certified mail. It is anticipated that the proposed drilling program will commence in early May following the two week public comment period.
- Completion of roadway remediation work: Spring 2010.
- Initiation of Gas Holder Discharge and Treatment: April 2010 (discharge commenced April 7, 2010).
- Gas Holder Demolition work: Summer/Fall 2010.
- Perform Data Reduction/Analysis (ongoing)

We trust that the above is acceptable. Please call me if you have any questions at 401-421-4140 Ext. 2719 or Michele Leone at 781-907-3651.

J:\ENV\43654.msk\Corresp\RIDEM Status Reports\43654 00 Memo-3.docx