

GZA GeoEnvironmental, Inc.

188 Valley Street, Suite 300


ovid	lence, I	Rhode Island 02909		Date: 6/08/2020 Job No. 03.0033554.04				
		0 (fax) 401.751.8613		Attention	: Mr. Joseph Ma	artella		
		•						
o:	Rhod	le Island Department of E	nvironmental Management	Re: Lique	faction Facility I	Project		
	Office	e of Land Revitalization ar	nd Sustainable Materials	STRA	P Perimeter Air	Quality Monit	oring (AQM)	
	Mana	agement		121 T	erminal Road/	642 Allens Ave	enue	
	235 P	Promenade Street		Provi	dence, Rhode Is	land		
	Provi	dence, Rhode Island 0290)8	Site R	emediation File	No. SR-28-11	.52	
e ar	e send	ling you:						
	S	Shop Drawings	X Attached	Chan	ge Order		Samples	
	C	Copy of Letter	Prints	Plans	5		Specifications	
	L	Jnder Separate Cover, the	e following Items:	via:				
	hipped:	•						
escr ir Q	X Via		Courier /2020, 6/03/2020, 6/04/2020 a AQM Station 4 Graph	Regula	r Mail	H	and Delivered/Pic	ked Up
escr ir Q	ription uality N of 6/0 AQ AQ	Monitoring (AQM) Results 1/2020 (6/01/2020, 6/02 QM Station/ 1 Graph QM Station 2 Graph			r Mail	H	and Delivered/Pic	ked Up
escr ir Q	ription uality N of 6/0 AQ AQ	Monitoring (AQM) Results 11/2020 (6/01/2020, 6/02 QM Station/ 1 Graph QM Station 2 Graph QM Station 3 Graph	. – /2020, 6/03/2020, 6/04/2020 a AQM Station 4 Graph AQM Station 5 Graph		r Mail	H	and Delivered/Pic	ked Up
escr ir Q	ription uality N of 6/0 AQ AQ	Monitoring (AQM) Results 11/2020 (6/01/2020, 6/02 QM Station/ 1 Graph QM Station 2 Graph QM Station 3 Graph	. – /2020, 6/03/2020, 6/04/2020 a AQM Station 4 Graph AQM Station 5 Graph		r Mail	H	and Delivered/Pio	ked Up
escriir Qi	X Via ription uality M < of 6/0 AQ AQ Sur	Monitoring (AQM) Results 11/2020 (6/01/2020, 6/02 QM Station/ 1 Graph QM Station 2 Graph QM Station 3 Graph	– /2020, 6/03/2020, 6/04/2020 a AQM Station 4 Graph AQM Station 5 Graph AQM Station 6 Graph		r Mail	H	and Delivered/Pio	ked Up
escr ir Qi Veek	X Via ription uality M c of 6/0 AQ AQ Sur	Monitoring (AQM) Results 01/2020 (6/01/2020, 6/02 QM Station/ 1 Graph QM Station 2 Graph QM Station 3 Graph mmary Figure	– /2020, 6/03/2020, 6/04/2020 a AQM Station 4 Graph AQM Station 5 Graph AQM Station 6 Graph	and 6/05/2020)		opies for Appr		ked Up
Descr sir Qi Veek	X Via ription uality M of 6/0 AQ AQ Sur ARE TR	Monitoring (AQM) Results 1/2020 (6/01/2020, 6/02 QM Station/ 1 Graph QM Station 2 Graph QM Station 3 Graph mmary Figure	Approved as Submit	and 6/05/2020)	Resubmit Co	opies for Appr	oval	ked Up
Descr Air Qu Week	X Via ription uality N c of 6/0 AQ AQ Sur ARE TR For A	Monitoring (AQM) Results 11/2020 (6/01/2020, 6/02 QM Station/ 1 Graph QM Station 2 Graph QM Station 3 Graph mmary Figure RANSMITTED as Checked Approval	– /2020, 6/03/2020, 6/04/2020 a AQM Station 4 Graph AQM Station 5 Graph AQM Station 6 Graph	and 6/05/2020)	Resubmit Co	opies for Appr es for Distribu	oval	ked Up
Descriir Quiveek	X Via ription uality M c of 6/0 AQ AQ Sur ARE TR For A For Y As Re	Monitoring (AQM) Results 01/2020 (6/01/2020, 6/02 QM Station/ 1 Graph QM Station 2 Graph QM Station 3 Graph mmary Figure	Approved as Submit	and 6/05/2020)	Resubmit Co Submit Copi Return Corro	opies for Appr es for Distribu	oval	ked Up
Descriir Qu Veek	X Via ription uality M c of 6/0 AQ AQ Sur ARE TR For A For Y As Re For R	Monitoring (AQM) Results 01/2020 (6/01/2020, 6/02) QM Station/ 1 Graph QM Station 2 Graph QM Station 3 Graph mmary Figure RANSMITTED as Checked Approval Your Use equested Review and Comment	Approved as Submit	and 6/05/2020)	Resubmit Co Submit Copi Return Corro	opies for Appr es for Distribu ected Prints	oval	ked Up
Descr Air Qu Week	X Via ription uality M c of 6/0 AQ AQ Sur ARE TR For A For Y As Re For R	Monitoring (AQM) Results p1/2020 (6/01/2020, 6/02 pM Station/ 1 Graph pM Station 2 Graph pM Station 3 Graph mmary Figure RANSMITTED as Checked Approval four Use equested	Approved as Submit	and 6/05/2020)	Resubmit Co Submit Copi Return Corro	opies for Appr es for Distribu ected Prints	oval	ked Up
Descr Air Qu Week	X Via ription uality M c of 6/0 AQ AQ Sur ARE TR For A For Y As Re For R	Monitoring (AQM) Results 01/2020 (6/01/2020, 6/02) QM Station/ 1 Graph QM Station 2 Graph QM Station 3 Graph mmary Figure RANSMITTED as Checked Approval Your Use equested Review and Comment	Approved as Submit	and 6/05/2020)	Resubmit Co Submit Copi Return Corro	opies for Appr es for Distribu ected Prints	oval	ked Up
Description Quality Qu	X Via ription uality M c of 6/0 AQ AQ Sur ARE TR For A For Y As Re For R	Monitoring (AQM) Results 01/2020 (6/01/2020, 6/02) QM Station/ 1 Graph QM Station 2 Graph QM Station 3 Graph mmary Figure RANSMITTED as Checked Approval Your Use equested Review and Comment	Approved as Submit	and 6/05/2020)	Resubmit Co Submit Copi Return Corro	opies for Appr es for Distribu ected Prints	oval	ked Up
Description Quality Qu	X Via ription uality M c of 6/0 AQ AQ Sur ARE TR For A For Y As Re FOR	Monitoring (AQM) Results 01/2020 (6/01/2020, 6/02) QM Station/ 1 Graph QM Station 2 Graph QM Station 3 Graph mmary Figure RANSMITTED as Checked Approval Your Use equested Review and Comment	Approved as Submit	and 6/05/2020)	Resubmit Co Submit Copi Return Corro	opies for Appr es for Distribu ected Prints	oval	ked Up
Description Quarter Qu	X Via ription uality M c of 6/0 AQ AQ Sur ARE TR For A For Y As Re FOR	Monitoring (AQM) Results 01/2020 (6/01/2020, 6/02) QM Station/ 1 Graph QM Station 2 Graph QM Station 3 Graph mmary Figure RANSMITTED as Checked Approval Your Use equested Review and Comment	Approved as Submit	and 6/05/2020)	Resubmit Co Submit Copi Return Corro	opies for Appr es for Distribu ected Prints	oval	ked Up
Description Quality Qu	X Via ription uality M c of 6/0 AQ AQ Sur ARE TR For A For Y As Re FOR	Monitoring (AQM) Results 01/2020 (6/01/2020, 6/02) QM Station/ 1 Graph QM Station 2 Graph QM Station 3 Graph mmary Figure RANSMITTED as Checked Approval Your Use equested Review and Comment	Approved as Submit	and 6/05/2020)	Resubmit Co Submit Copi Return Corro	opies for Appr es for Distribu ected Prints	oval	ked Up
Description Quality Qu	X Via ription uality M c of 6/0 AQ AQ Sur ARE TR For A For Y As Re FOR FOR	Monitoring (AQM) Results 01/2020 (6/01/2020, 6/02 QM Station/ 1 Graph QM Station 2 Graph QM Station 3 Graph mmary Figure RANSMITTED as Checked Approval Your Use equested Review and Comment BIDS DUE:	AQM Station 6 Graph AQM Station 6 Graph AQM Station 6 Graph APproved as Submit Approved as Noted Returned for Correct	and 6/05/2020)	Resubmit Co Submit Copi Return Corr PRINTS RETU	opies for Appr es for Distribu ected Prints JRNED AFTER	oval	ked Up
Description Quality Qu	X Via ription uality M c of 6/0 AQ AQ Sur ARE TR For A For Y As Re FOR FOR	Monitoring (AQM) Results 01/2020 (6/01/2020, 6/02) QM Station/ 1 Graph QM Station 2 Graph QM Station 3 Graph mmary Figure RANSMITTED as Checked Approval Your Use equested Review and Comment	Approved as Submit Approved as Noted Returned for Correct	and 6/05/2020)	Resubmit Co Submit Copi Return Corro PRINTS RETU	opies for Appr es for Distribu ected Prints JRNED AFTER	oval Ition LOAN TO US	ked Up

TRANSMITTAL

Liquefaction Facility Project -

STRAP Perimeter Air Quality Monitoring (AQM)

121 Terminal Road / 642 Allens Avenue, Providence, Rhode Island



Date	Time	Constituent	Observed Range of Sustained Readings	Response Actions Performed
None				

E	quipment Notes
	None


Data Summary Statistics				
TVOCs average concentration	0.02	ppm		
TVOCs maximum concentration	3.44	ppm		
TVOCs action level	1	ppm		
PM10 average concentration	17.63	μg/m³		
PM10 maximum concentration	123.00	μg/m³		
PM10 action level	150	μg/m³		

- 1) Transient readings were conducted over a one minute time period. A reading is sustained if it is held for over a five minute time period.
- 2) The location of each AQM Station is presented on the attached summary figure.
- 3) Air quality monitoring performed in accordance with the May 12, 2017 Short Term Response Action Plan (STRAP), the October 11, 2017 STRAP Addendum (including Attachment N Clarifications to the Proposed Air Monitoring Program for STRAP Activities) and the October 27, 2017 Short Term Response Action Approval Letter issued by RIDEM. Monitoring conducted during active STRAP activities.

Liquefaction Facility Project -

STRAP Perimeter Air Quality Monitoring (AQM)

121 Terminal Road / 642 Allens Avenue, Providence, Rhode Island



Date	Time	Constituent	Observed Range of Sustained Readings	Response Actions Performed
None				

Equipment Notes	
None	


Data Summary Statistics				
TVOCs average concentration	0.05	ppm		
TVOCs maximum concentration	0.70	ppm		
TVOCs action level	1	ppm		
PM10 average concentration	20.05	μg/m³		
PM10 maximum concentration	182.35	μg/m³		
PM10 action level	150	μg/m³		

- 1) Transient readings were conducted over a one minute time period. A reading is sustained if it is held for over a five minute time period.
- 2) The location of each AQM Station is presented on the attached summary figure.
- 3) Air quality monitoring performed in accordance with the May 12, 2017 Short Term Response Action Plan (STRAP), the October 11, 2017 STRAP Addendum (including Attachment N Clarifications to the Proposed Air Monitoring Program for STRAP Activities) and the October 27, 2017 Short Term Response Action Approval Letter issued by RIDEM. Monitoring conducted during active STRAP activities.

Liquefaction Facility Project -

STRAP Perimeter Air Quality Monitoring (AQM)

121 Terminal Road / 642 Allens Avenue, Providence, Rhode Island



Date	Time	Constituent	Observed Range of Sustained Readings	Response Actions Performed
6/2/2020	08:58-09:03	Dust	169.50- 334.54 μg/m3	No actions taken because the readings were not attributed to site work.

Equipment Notes	
None	


Data Summary St	atistics	
TVOCs average concentration	0.02	ppm
TVOCs maximum concentration	0.58	ppm
TVOCs action level	1	ppm
PM10 average concentration	13.40	$\mu g/m^3$
PM10 maximum concentration	334.54	$\mu g/m^3$
PM10 action level	150	μg/m³

- 1) Transient readings were conducted over a one minute time period. A reading is sustained if it is held for over a five minute time period.
- 2) The location of each AQM Station is presented on the attached summary figure.
- 3) Air quality monitoring performed in accordance with the May 12, 2017 Short Term Response Action Plan (STRAP Addendum (including Attachment N Clarifications to the Proposed Air Monitoring Program for STRAP Activities) and the October 27, 2017 Short Term Response Action Approval Letter issued by RIDEM. Monitoring conducted during activities.

Liquefaction Facility Project -

STRAP Perimeter Air Quality Monitoring (AQM)

121 Terminal Road / 642 Allens Avenue, Providence, Rhode Island



Date	Time	Constituent	Observed Range of Sustained Readings	Response Actions Performed
None				

Equipment Notes	
None	


Data Summary Statistics				
TVOCs average concentration	0.03	ppm		
TVOCs maximum concentration	0.17	ppm		
TVOCs action level	1	ppm		
PM10 average concentration	16.88	μg/m³		
PM10 maximum concentration	65.26	$\mu g/m^3$		
PM10 action level	150	μg/m³		

- 1) Transient readings were conducted over a one minute time period. A reading is sustained if it is held for over a five minute time period.
- 2) The location of each AQM Station is presented on the attached summary figure.
- 3) Air quality monitoring performed in accordance with the May 12, 2017 Short Term Response Action Plan (STRAP), the October 11, 2017 STRAP Addendum (including Attachment N Clarifications to the Proposed Air Monitoring Program for STRAP Activities) and the October 27, 2017 Short Term Response Action Approval Letter issued by RIDEM. Monitoring conducted during active STRAP activities.

Liquefaction Facility Project -

STRAP Perimeter Air Quality Monitoring (AQM)

121 Terminal Road / 642 Allens Avenue, Providence, Rhode Island



Dat	e	Time	Constituent Observed Range of Sustained Readings		Response Actions Performed
Nor	ne		•		

Equipment Notes		
None		


Data Summary Statistics				
TVOCs average concentration	0.01	ppm		
TVOCs maximum concentration	0.15	ppm		
TVOCs action level	1	ppm		
PM10 average concentration	15.53	μg/m³		
PM10 maximum concentration	59.38	μg/m³		
PM10 action level	150	μg/m³		

- 1) Transient readings were conducted over a one minute time period. A reading is sustained if it is held for over a five minute time period.
- 2) The location of each AQM Station is presented on the attached summary figure.
- 3) Air quality monitoring performed in accordance with the May 12, 2017 Short Term Response Action Plan (STRAP), the October 11, 2017 STRAP Addendum (including Attachment N Clarifications to the Proposed Air Monitoring Program for STRAP Activities) and the October 27, 2017 Short Term Response Action Approval Letter issued by RIDEM. Monitoring conducted during active STRAP activities.

Liquefaction Facility Project -

STRAP Perimeter Air Quality Monitoring (AQM)

121 Terminal Road / 642 Allens Avenue, Providence, Rhode Island



Date	Time	Constituent	Observed Range of Sustained Readings	Response Actions Performed
None	-	•		

Equipment Notes	
None	

Data Summary Statistics				
TVOCs average concentration	0.05	ppm		
TVOCs maximum concentration	0.23	ppm		
TVOCs action level	1	ppm		
PM10 average concentration	17.72	μg/m³		
PM10 maximum concentration	57.58	μg/m³		
PM10 action level	150	μg/m³		

- 1) Transient readings were conducted over a one minute time period. A reading is sustained if it is held for over a five minute time period.
- 2) The location of each AQM Station is presented on the attached summary figure.
- 3) Air quality monitoring performed in accordance with the May 12, 2017 Short Term Response Action Plan (STRAP), the October 11, 2017 STRAP Addendum (including Attachment N Clarifications to the Proposed Air Monitoring Program for STRAP Activities) and the October 27, 2017 Short Term Response Action Approval Letter issued by RIDEM. Monitoring conducted during active STRAP activities.



642 ALLENS AVENUE FORMER MGP SITE


PROJECT WORK SITE

STRAP AREA (LIMITS OF GROUNDWATER AND SOIL DISTURBANCE)

AIR QUALITY MONITORING (AQM) STATION

REFERENCE NOTES:

- BASE MAP DEVELOPED FROM A GOOGLE
 PROFESSIONAL ELECTRONIC IMAGE FILE. DIGITAL
 AERIAL ORTHOPHOTOGRAPHY WAS PUBLISHED IN
 FEBRUARY 2018.
- 2. SITE BOUNDARIES ARE APPROXIMATE.
- 3. PERIMETER AIR MONITORING PROGRAM CONDUCTED AS DESCRIBED IN THE MAY 12, 2017 SHORT TERM RESPONSE ACTION PLAN (STRAP) AND OCTOBER 11, 2017 STRAP ADDENDUM, WHICH WERE APPROVED BY RIDEM WITH THE OCTOBER 27, 2017 STRAP APPROVAL.



THE INFORMATION SHOWN ON THE DRAWING IS SOLELY FOR USE BY NATIONAL GRID OR THE NATIONAL GRID'S DESIGNATED REPRESENTATIVE FOR THE SPECIFIC PROJECT AND LOCATION IDENTIFIED ON THE DRAWING. THE DRAWING SHALL NOT BE TRANSFERRED, REUSED, COPIED, OR ALTERED IN ANY MANNER FOR SEA TANY OTHER LOCATION OR FOR ANY OTHER PURPOSE WITHOUT THE PRIOR WRITTEN CONSENT OF GZA AND NATIONAL GRID, WILL BE DRAWING BY OTHERS, WITHOUT THE PRIOR WRITTEN EXPRESS CONSENT OF GZA AND NATIONAL GRID, WILL BE AT THE USER'S SOLE RISK AND WITHOUT ANY PART OF THE PRIOR WRITTEN EXPRESS CONSENT OF GZA AND NATIONAL GRID, WILL BE AT THE USER'S SOLE RISK AND WITHOUT ANY PART OF THE PRIOR OF THE PRIOR

NATIONAL GRID LIQUEFACTION FACILITY PERIMETER AIR MONITORING PROGRAM PROVIDENCE, RHODE ISLAND

Summary Figure Week of 6-01-2020

PREPARED BY:				PREPARED FOR:		
GZA GeoEnvironmental, Inc. Engineers and Scientists www.gza.com			national grid			
PROJ MGR:	SDN	REVIEWED BY:	MSK	CHECKED BY	: MSK	FIGURE
DESIGNED BY:	SDN	DRAWN BY:	LDT	SCALE: A	S NOTED	4
DATE: PROJECT NO			REVISION I	NO.		
W/O 6-01-2020		33554.0	04	(SHEET NO.