

**Department of Environmental Management
Office of Waste Management**

FIELD INVESTIGATION REPORT

Facility Name: Portsmouth Town Dump
Date of Investigation: 3/23/2017
Facility Address: East Main Road, Portsmouth

Investigators: Bob Schmidt, Office of Waste Management

Findings:

Again this week DEM received a complaint about dirt on the road adjacent to the site. Mark Dennen requested that I visit the site to photograph the area near the access road to the landfill closure project. I arrived and took six photographs at approximately 11:15 a.m.. The images show that dirt is indeed being tracked out of the facility onto the public roadway. Two images of the rock lined access road show heavy silt buildup and a water truck on site. No dust or odors were evident at the time of inspection.

I left the site at approximately 11:25 a.m..





Bob Schmidt
Bob Schmidt

3-24-2017
Date