RI Department of Environmental Management Environmental Land Usage Restriction (ELUR) Annual Compliance Evaluation Form

(Please type or print)

| Site Name: Gorham Park | _ Property Owner: City of Providence, Parks Dept |
|--|---|
| RIDEM File No.: 00169986 | |
| RIDEM Project Manager: Joseph Martella | |
| ELUR Recording Date: _June 15, 2017 | |
| Owner Telephone Number: 401 680 7200 | |
| | ot appropriate for use on sites that require the use SDS, ongoing air or groundwater monitoring, etc.) atted by the Department. |
| 1. Site Description | |
| a. Site Address: 425 Adelaide Avenue | |
| Providence, RI 02907 | |
| b. Plat:51 | |
| c. Is the ELUR applicable to the entire site? X Yes No If no, please describe the portion of the entire site? d. What does the ELUR restrict? (Select all | the property subject to the ELUR: |
| X Residential Uses | mat appry) |
| X Groundwater | |
| X Exposure to Site Soils | |
| X Infiltration of Water | |
| X Subsurface Structures X Other (Please Explain): Cutting of | vegetation within 60 ft of Mashapaug Pond/Cove |
| 2. Groundwater | |
| a. Are there any known or observed ground Yes X No | water wells present? |
| b. Are these well(s) used for drinking water Yes No X_ No | |
| If no, please state what they are used | d for (i.e. irrigation, cooling, etc.): |

| C. | X Yes No |
|-------|---|
| 3. En | gineered Controls (e.g. asphalt, concrete, building foundations, landscaped areas, etc.) |
| a. | Please provide a brief description of the engineered control(s) (e.g. building foundations, one foot of clean fill over a geotextile liner, etc.): 12" clean fill placed over non-woven geo-textile marker fabric on field areas. 6" clean fill, 4" aggregate base and 2" stone dust over non-woven |
| | geo-textile marker fabric on 4' wide pathways. |
| b. | Overall Condition of Engineered Control(s) |
| | Acceptable Not Applicable (Sites where only groundwater is restricted) |
| c. | Are there any areas on the property that have broken concrete, cracked asphalt, potholes, eroded landscaping, etc.? X_YesNo |
| | If yes: |
| | Please provide a description of the area(s) of concern: Broken down asphalt inUtility right of way @ NW corner of Parcel C. |
| | Could water infiltrate through these areas into underlying contaminated soils? Yes No X_ N/A; Infiltration Not Restricted |
| | When will the area(s) of concern be repaired? |
| d. | Have there been any soil disturbances or excavations into the cap (engineered control) in the last year? |
| | If yes: Please refer to Closure report dated 11.8.2019 |
| | How large was the area of disturbance? |
| | Please provide the reason or cause for disturbance or excavation: Development of 4' wide stone dust pathway, Site entry and bench and signage locations as |
| | part of passive park improvements |

Was this disturbance or excavation approved by the Department?

| | X Yes, Date of Approval: |
|----|--|
| | No |
| | N/A |
| | Was the Soil Management Plan (SMP) properly followed? |
| | X Yes No N/A |
| | |
| | If no, please explain: |
| | Was any soil taken offsite? Yes X_ No N/A |
| e. | Within the past year has there been any construction at the property unauthorized by the department? Yes X No |
| | If yes: |
| | Please explain: |
| | Did this construction disturb site soils, the existing building or capped surfaces (asphalt concrete, or landscaped areas)? YesX_No If yes, please specify: |
| | |
| f. | Have there been any subsurface structures (underground storage tanks, below grade foundations, septic systems, storm water systems, french drains, etc.) constructed or installed since the remediation was completed? Yes X No |
| | If yes: |
| | Please Explain: |
| | Was permission of the Department's Office of Waste Management obtained? Yes, Date of Approval: No |

| g. | X Good Acceptable Non-compliant N/A |
|----------------|---|
| h. | Does the cap effectively limit exposure to contaminated subsurface soil? X Yes No NA |
| 4. Pr | operty Use |
| a. | Are there any residential uses on the property (i.e. houses, apartments or condominiums etc.) that were not previously approved by the Department? Yes X_ No Residential Use is Permitted |
| | If yes, please explain: |
| b. | Are there any schools, daycare facilities or recreational facilities on the property that have not been approved by the Department? Yes X No Residential Use is Permitted |
| | If yes, please explain: |
| c. | Has the property use changed in any way since the ELUR was recorded? X Yes No If yes, please explain: Please refer to Closure Report dated 11.8.19 |
| | If yes, please explain:Please refer to Closure Report dated 11.6.19 |
| 5. Fe i | ncing (if applicable) |
| a. | Overall Condition of the Fencing X Good Acceptable Non-compliant No Fence Required |
| b. | Does the fencing effectively limit the ELUR area? X Yes No N/A |
| 6. Ov | verall Assessment |
| Do | pes this site meet the standard imposed in the ELUR? X Compliant Non-compliant |

| 8. Please attach photos that document compliance with the ELUR, potential areas of concern, and the current state of the engineered controls. | Please see | Attachment | A - ELUR Ar | nual Comr | liance Evalu | ation Photos | | |
|---|--------------------------------|------------------------------|-------------------------|-------------------------|---------------------|---------------|--------------|-----------------|
| 8. Please attach photos that document compliance with the ELUR, potential areas of concern, and the current state of the engineered controls. | 1 10400 000 | 7 tttaoriiriorit 7 | LLOITA | indai Oomp | marioo Evalu | ation i notoc | | |
| 8. Please attach photos that document compliance with the ELUR, potential areas of concern, and the current state of the engineered controls. | | | | | | | | |
| 8. Please attach photos that document compliance with the ELUR, potential areas of concern, and the current state of the engineered controls. | | | | | | | | |
| 8. Please attach photos that document compliance with the ELUR, potential areas of concern, and the current state of the engineered controls. | | | | | | | | |
| 8. Please attach photos that document compliance with the ELUR, potential areas of concern, and the current state of the engineered controls. | | | | | | | | |
| 8. Please attach photos that document compliance with the ELUR, potential areas of concern, and the current state of the engineered controls. | | | | | | | | |
| 8. Please attach photos that document compliance with the ELUR, potential areas of concern, and the current state of the engineered controls. | | | | | | | | |
| 8. Please attach photos that document compliance with the ELUR, potential areas of concern, and the current state of the engineered controls. | | | | | | | | |
| 8. Please attach photos that document compliance with the ELUR, potential areas of concern, and the current state of the engineered controls. | | | | | | | | |
| 8. Please attach photos that document compliance with the ELUR, potential areas of concern, and the current state of the engineered controls. | | | | | | | | |
| 8. Please attach photos that document compliance with the ELUR, potential areas of concern, and the current state of the engineered controls. | | | | | | | | |
| 8. Please attach photos that document compliance with the ELUR, potential areas of concern, and the current state of the engineered controls. | | | | | | | | |
| 8. Please attach photos that document compliance with the ELUR, potential areas of concern, and the current state of the engineered controls. | | | | | | | | |
| 8. Please attach photos that document compliance with the ELUR, potential areas of concern, and the current state of the engineered controls. | | | | | | | | |
| 8. Please attach photos that document compliance with the ELUR, potential areas of concern, and the current state of the engineered controls. | | | | | | | | |
| 8. Please attach photos that document compliance with the ELUR, potential areas of concern, and the current state of the engineered controls. | | | | | | | | |
| 8. Please attach photos that document compliance with the ELUR, potential areas of concern, and the current state of the engineered controls. | | | | | | | | |
| 8. Please attach photos that document comphance with the ELUK, potential areas of concern, and the current state of the engineered controls. | | | | | | | | |
| and the current state of the engineered controls. | 0 Di - 44 | | | , | | | | 0 |
| | 8. Please atta | ch photos t | hat docum | ent comp | iance with | the ELUR, | potential ar | eas of concern, |
| | 8. Please atta and the curr | ch photos t ent state of | hat docum | ent compleered cont | iance with rols. | the ELUR, | potential ar | eas of concern, |
| | 8. Please atta and the curr | ich photos t ent state of | hat docum | ent comp eered cont | iance with rols. | the ELUR, | potential ar | eas of concern, |
| | 8. Please atta and the curr | ch photos t ent state of | hat docum the engine | ent compleered cont | iance with rols. | the ELUR, | potential ar | eas of concern, |
| | 8. Please atta and the curr | ich photos t ent state of | hat docum the engine | ent comp eered cont | iance with rols. | the ELUR, | potential ar | eas of concern, |
| | 8. Please atta and the curr | ich photos t ent state of | hat docum the engine | ent compl eered cont | iance with rols. | the ELUR, | potential ar | eas of concern, |
| | 8. Please atta and the curr | ich photos t ent state of | hat docum the engine | ent comp eered cont | iance with rols. | the ELUR, | potential ar | eas of concern, |
| | 8. Please atta and the curr | ch photos t ent state of | that docum | ent compleered cont | iance with rols. | the ELUR, | potential ar | eas of concern, |
| | 8. Please atta and the curr | ich photos t ent state of | hat docum | ent comp eered cont | iance with rols. | the ELUR, | potential ar | eas of concern, |
| | 8. Please atta and the curr | ch photos t ent state of | chat docum | ent comp eered cont | iance with rols. | the ELUR, | potential ar | eas of concern, |
| | 8. Please atta and the curr | ich photos t ent state of | hat docum the engine | ent comp eered cont | iance with rols. | the ELUR, | potential ar | eas of concern, |
| | 8. Please atta and the curr | ich photos t ent state of | chat docum | ent comp eered cont | iance with rols. | the ELUR, | potential ar | eas of concern, |
| | 8. Please atta and the curr | ch photos t ent state of | that docum | ent comp eered cont | iance with rols. | the ELUR, | potential ar | eas of concern, |
| | 8. Please atta and the curr | ich photos t ent state of | chat docum | ent comp eered cont | iance with rols. | the ELUR, | potential ar | eas of concern, |
| | 8. Please atta and the curr | ch photos t ent state of | chat docum | ent comp eered cont | iance with rols. | the ELUR, | potential ar | eas of concern, |
| | 8. Please atta and the curr | ich photos t ent state of | chat docum | ent comp eered cont | iance with rols. | the ELUR, | potential ar | eas of concern, |
| | 8. Please atta and the curr | ch photos t ent state of | chat docum | ent comp eered cont | iance with rols. | the ELUR, | potential ar | eas of concern, |
| | 8. Please atta and the curr | ch photos t ent state of | that docum | ent comp eered cont | iance with rols. | the ELUR, | potential ar | eas of concern, |

Wendy Nilsson certify to the best of my knowledge that this Annual Compliance Evaluation Form is a complete and an accurate representation of the site and contains all known facts concerning the Environmental Land Use Restriction imposed on the site. City of Providence Parks Department Owning Company (If applicable) Signature Superintendent of Parks Wendy Nilsson Printed Name Title December 9, 2019 Date 401.680.7200 wnilsson@providenceri.gov Telephone Number **Email Address** Certification of the Inspector (if different than Owner) certify to the best of my knowledge that this Annual Compliance Evaluation Form is a complete and accurate representation of the site and contains all known facts concerning the Environmental Land Use Restriction imposed on the site. Environmental Company Name Signature Printed Name Title Contact Information (If Applicable) Telephone Number Email Address

Certification of Property Owner

GORHAM PARK IMPROVEMENTS (AKA MASHAPAUG POND PARK)

425 ADELAIDE AVENUE, PROVIDENCE, R.I. 02907

ENVIRONMENTAL LAND USAGE RESTRICTION: ANNUAL COMPLIANCE EVALUATION PHOTOS (NOV. 2019)

Southern Field Cap - adjacent to Alvarez High School



Mashapaug Inner Cove Embankment



Northern Field Cap with Signage and Walking Trail



Environmental Monitoring Wells, Mashapaug Inner Cove Embankment





Perimeter Fencing, School, Parking Lot, Commercial Property, Stormwater Detention Basin

